



P144-00174 P144-00175

P144-00176











GEARED-UP AXIAL DRIVEN TOOL, H=100 EXTERNAL COOLANT, RATIO 1:2, (8,000 RPM)

Tool No.	Spindle	Α	В	С
P144-00174	ER25	98.06	52.5	
P144-00176	ER25 + ER16	98.06	52.5	82.75

GEARED-UP AXIAL TOOL, H=100 COOLANT THROUGH*, RATIO 1:2, (8,000 RPM)

Tool No.	Spindle	Α	В	С
P144-00175	ER25	98.06	77.5	

*Coolant Through tools are designed for 1000 psi.
They require 5 Micorn Filtration and CANNOT be run dry.